B.R No. 495/2014-15 Dated: 28.02.2015

Inspection report for the Work of: Improvements and Asphalting to Bloom Field Roads in Ward No. 10, Vidyarnyapura Sub Division.

By,

Sri K. Manjunath

Inspection Report

Name of Work	:	Improvements and Asphalting to Bloom Field Roads in Ward No. 10, Vidyarnyapura Sub Division.
Work Order	:	EE/BTP/BBMP/KRIDL/WO/676/2013-14 Dated: 05.03.2014.
Agency	:	Technical Manager, KRIDL
B.R. No & Date	:	495/2014-15 Dated: 28.02.2015
Bill Amount	:	19,98,690.40
Job Code	:	010-14-000010
P. Code	:	P-1771
Date of Inspection	:	25-02-2016

The above said work Improvements and Asphalting to Bloom Field Roads in ward no 10 Vidyaranyapura Jabsan was shown to me by the Concerned A.E. Sri Madhusudan.

The above said work was inspected by me along with the Concerned A.E.

The measurements at some locations were verified and found Satisfactory.

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Sketch Showing the Work of Improvements and Asphalting to Bloom Field Roads in Ward No. 10, Vidyarnyapura Sub Division.

Assistant Engineer
Ward No. 10

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (R&D)
PUBLIC WORKS DEPARTMENT

Photos Showing the work of Improvements and Asphalting to Bloom Field Roads in Ward No. 10, Vidyarnyapura Sub Division.



MANJUNATH
DQM BE (Civil)
EXECUTIVE ENGINEER
PUBLIC WORKS DEPARTMENT

AE

Photos Showing the work of Improvements and Asphalting to Bloom Field Roads in Ward No. 10, Vidyarnyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

AE